00839.000466.



PATENT COSÉ

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re.Patent of:)
JINSHO MATSUYAMA	Examiner: Vinh P. Nguyen Group Art Unit: 2829
Appl. No.: 10/627,923	
Filed: July 28, 2003	· ·
For: METHOD AND APPARATUS FOR MEASURING PHOTOELECTRIC CONVERSION DEVICE, AND PROCESS AND APPARATUS FOR PRODUCING PHOTOELECTRIC CONVERSION DEVICE	Certificate JAN 1 0 2006 of Correction
U.S. Patent No.: US 6,946,858 B2) :
Issued: September 20, 2005) :) January 5, 2006

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

81/09/2006 JADDO1 99000003 6946858

Accompanying this letter is a check for \$100.00 to cover the statutory fee

for such Certificate of Correction.

WAN 11 2005

Patentee's undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

John A. Krause

Attorney for Patentee Registration No. 24,613

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 Facsimile: (212) 218-2200

PATENT NO.

US 6,946,858 B2

DATED

SEPTEMBER 20, 2005

INVENTOR(S) :

JINSHO MATSUYAMA

Page 1 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1

Line 12, "as" should read --as a--; and Line 28, "wherein" should read --wherein an--.

COLUMN 2

Line 12, "entire" should read --entire area--.

COLUMN 3

Line 33, "enspective" should read --inspective--.

COLUMN 4

Line 16, "respect" should read --respect to--;
Line 38, "device" should read --device,--;
Line 39, "large" should read --large,--;
Line 41, "film" should read --film,--;
Line 47, "FIG. 7" should read --FIG. 7,--;
Line 66, "condition" should read --conditions--; and
Line 67, "unstable" should read --unstable,--; and "sunlight" should read --sunlight,--.

COLUMN 5

Line 2, "apparatus" should read --apparatus,--; Line 3, "characteristics" should read --characteristics,--; Line 4, "light" should read --light,--; and Line 5, "unstable" should read --unstable,--; and "sunlight" should read --sunlight,--.

COLUMN 8

Line 3, "description" should read --a description--; Line 49, "can" should read --can be--; and Line 67, "those" should read --whose--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

PATENT NO. US 6,946,858 B2

No. of add'l. copies @ 30¢ per page

MAN 11 2006

PATENT NO.

US 6,946,858 B2

DATED

SEPTEMBER 20, 2005

INVENTOR(S) :

JINSHO MATSUYAMA

Page 2 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 9

Line 1, "respect" should read --respect to--; Line 20, "an" should read --in--; Line 25, "intention" should read --invention--; and Line 58, "there" should read --where--.

COLUMN 11

Line 25, "other" should read --another--; Line 42, "Mismatch" should read --mismatch--; Line 53, "Qs(λ);" should read --Qs(λ):--; and Line 56, "where" should read --with--.

COLUMN 12

Line 9, "current voltage" should read --current-voltage--.

COLUMN 13

Line 25, "ref rence" should read --reference--; Line 42, "similar 3" should read --similar--; and Line 63, "make" should read --taken--.

COLUMN 14

Line 2, "deviation" should read --of a deviation--; Line 10, "possible" should read --possible to have--; Line 26, "(6)" should read --(6).--; Line 48, "means" should read --mean--; Line 65, "lager." should read --larger.--; and Line 67, "designed" should read --design--.

COLUMN 15

Line 6, "below" should read --below.--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

PATENT NO. <u>US 6,946,858 B2</u>

No. of add'l. copies @ 30¢ per page



JAN 11 2006

PATENT NO.

US 6,946,858 B2

DATED

SEPTEMBER 20, 2005

INVENTOR(S) :

JINSHO MATSUYAMA

Page 3 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 16

Line 2, "pair" should read --a pair--; Line 6, "measures" should read --measured--; and Line 47, "made" should read --made to--.

COLUMN 17

Line 39, "be also" should read --also be--; Line 64, "at" should read --at an--; and Line 66, "thereafter" should read --thereafter.--.

COLUMN 18

Line 5, "be always" should read --always be--; Line 6, "be" should read --always--; Line 7, "always and" should read --be--; and "refrain" should read --refrain from--; and Line 13, "refraining" should read --refraining from--; Line 26, "step, the" should read --step. The--; and Line 41, "refrain" should read --refrain from--.

COLUMN 19

Line 21, "cells" should read --cells to--.

COLUMN 20

Line 54, "call" should read --cell--; and Line 66, "be also" should read --also be--.

COLUMN 21

Line 5, "performed." should read --is performed.--; Line 19, "aforesaid" should read --the aforesaid--; and Line 61, "fired" should read --fixed--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

NY MAIN 543860v1

PATENT NO. <u>US 6,946,858 B2</u>

No. of add'l. copies @ 30¢ per page



PATENT NO.

US 6,946,858 B2

DATED

SEPTEMBER 20, 2005

INVENTOR(S) :

JINSHO MATSUYAMA

Page 4 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 22

Line 17, "expression" should read --expression is--.

COLUMN 25

Line 60, "Well" should read --well--; and Line 63, "wide" should read --side--.

COLUMN 26

Line 26, "cmx42 cam" should read --cmx 42 cm,--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

PATENT NO. <u>US 6,946,858 B2</u>

No. of add'l. copies @ 30¢ per page



PATENT NO.

US 6,946,858 B2

DATED

SEPTEMBER 20, 2005

INVENTOR(S) :

JINSHO MATSUYAMA

Page 1 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1

Line 12, "as" should read --as a--; and Line 28, "wherein" should read --wherein an--.

COLUMN 2

Line 12, "entire" should read --entire area--.

COLUMN 3

Line 33, "enspective" should read --inspective--.

COLUMN 4

Line 16, "respect" should read --respect to--;
Line 38, "device" should read --device,--;
Line 39, "large" should read --large,--;
Line 41, "film" should read --film,--;
Line 47, "FIG. 7" should read --FIG. 7,--;
Line 66, "condition" should read --conditions--; and
Line 67, "unstable" should read --unstable,--; and "sunlight" should read --sunlight,--.

COLUMN 5

Line 2, "apparatus" should read --apparatus,--; Line 3, "characteristics" should read --characteristics,--; Line 4, "light" should read --light,--; and Line 5, "unstable" should read --unstable,--; and "sunlight" should read --sunlight,--.

COLUMN 8

Line 3, "description" should read --a description--; Line 49, "can" should read --can be--; and Line 67, "those" should read --whose--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

NY_MAIN 543860v1

PATENT NO. US 6,946,858 B2

No. of add'l. copies @ 30¢ per page



JAN 11 2006

PATENT NO.

US 6,946,858 B2

DATED

SEPTEMBER 20, 2005

INVENTOR(S) :

JINSHO MATSUYAMA

Page 2 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 9

Line 1, "respect" should read --respect to--; Line 20, "an" should read --in--; Line 25, "intention" should read --invention--; and Line 58, "there" should read --where--.

COLUMN 11

Line 25, "other" should read --another--; Line 42, "Mismatch" should read --mismatch--; Line 53, "Qs(λ);" should read --Qs(λ):--; and Line 56, "where" should read --with--.

COLUMN 12

Line 9, "current voltage" should read --current-voltage--.

COLUMN 13

Line 25, "ref rence" should read --reference--; Line 42, "similar 3" should read --similar--; and Line 63, "make" should read --taken--.

COLUMN 14

Line 2, "deviation" should read --of a deviation--; Line 10, "possible" should read --possible to have--; Line 26, "(6)" should read --(6).--; Line 48, "means" should read --mean--; Line 65, "lager." should read --larger.--; and Line 67, "designed" should read --design--.

COLUMN 15

Line 6, "below" should read --below.--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

PATENT NO. <u>US 6,946,858 B2</u>

No. of add'l. copies @ 30¢ per page

JAN 11 2006

NY_MAIN 543860v1

PATENT NO.

US 6,946,858 B2

DATED

SEPTEMBER 20, 2005

INVENTOR(S) :

JINSHO MATSUYAMA

Page 3 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 16

Line 2, "pair" should read --a pair--; Line 6, "measures" should read --measured--; and Line 47, "made" should read --made to--.

COLUMN 17

Line 39, "be also" should read --also be--; Line 64, "at" should read --at an--; and Line 66, "thereafter" should read --thereafter.--.

COLUMN 18

Line 5, "be always" should read --always be--; Line 6, "be" should read --always--; Line 7, "always and" should read --be--; and "refrain" should read --refrain from--; and Line 13, "refraining" should read --refraining from--; Line 26, "step, the" should read --step. The--; and Line 41, "refrain" should read --refrain from--.

COLUMN 19

Line 21, "cells" should read --cells to--.

COLUMN 20

Line 54, "call" should read --cell--; and Line 66, "be also" should read --also be--.

COLUMN 21

Line 5, "performed." should read --is performed.--; Line 19, "aforesaid" should read --the aforesaid--; and Line 61, "fired" should read --fixed--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

NY_MAIN 543860v1

PATENT NO. US 6,946,858 B2

No. of add'l. copies @ 30¢ per page

JAN 11 2006

PATENT NO.

US 6,946,858 B2

DATED

SEPTEMBER 20, 2005

INVENTOR(S) :

JINSHO MATSUYAMA

Page 4 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 22

Line 17, "expression" should read --expression is--.

COLUMN 25

Line 60, "Well" should read --well--; and Line 63, "wide" should read --side--.

COLUMN 26

Line 26, "cmx42 cam" should read --cmx 42 cm,--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

PATENT NO. <u>US 6,946,858 B2</u>

No. of add'l. copies @ 30¢ per page

